

CE ۱∛¢) US

Model Number

PMI120-F90-IU-V1

Features

- Analog output 0 V ... 10 V/4 mA 20 mÀ
- Measuring range 0 ... 120 mm •

Technical data	
General specifications	
Switching element function	analog, current or voltage output
Object distance	0.5 3 mm , recommended: 2 mm
Measurement range	0 120 mm
Linearity range	1 119 mm
Nominal ratings	
Operating voltage U _B	18 30 V DC
Reverse polarity protection	reverse polarity protected
Linearity error	within measuring range: \pm 0.8 mm within linearity range: \pm 0.4 mm
Repeat accuracy	± 0.1 mm
Resolution	125 μm
Temperature drift	± 0.5 mm (-25 °C 70 °C)
No-load supply current I0	≤ 40 mA
Operating voltage display	LED green
Analog output	
Output type	1 current output: 4 20 mA 1 voltage output: 0 10 V
Load resistor	current output: \leq 400 Ω voltage output: \geq 1000 Ω
Short-circuit protection	voltage output: pulsing
Ambient conditions	
Ambient temperature	-25 70 °C (-13 158 °F)
Mechanical specifications	
Connection type	connector M12 x 1, 4-pin
Protection degree	IP67
Material	
Housing	ABS
Target	mild steel, e. g. 1.0037, SR235JR (formerly St37-2)
Compliance with standards and directives	
Standard conformity	
Standards	EN 60947-5-2:2007 IEC 60947-5-2:2007 EN 60947-5-7:2003 IEC 60947-5-7:2003

Approvals and certificates

UL approval CCC approval cULus Listed, General Purpose, Class 2 Power Source CCC approval / marking not required for products rated ≤36 V

Dimensions



Release date: 2013-06-11 15:31 Date of issue: 2013-06-11 191136_eng.xml Refer to "General Notes Relating to Pepperl+Fuchs Product Information"

Pepperl+Fuchs Group www.pepperl-fuchs.com

USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com



1

Additional Information Electrical Connection IU dimensions for the target object: I (BN . L IF 4(BK) I 4-20 mA 2(WH) 蝍 0-10 \ 3(BU) - UB Core colours in accordance with EN 60947-5-2. Pinout 0 V/4 m/ 10 V/20 m/ Linearity range Measuring range Wire colors in accordance with EN 60947-5-2 BN (brown) 1 2 WΗ (white) 3 ΒU (blue) 4 BK (black) Accessories **BT-F90-W** Damping element; lateral screw holes **MH-F90** Mounting bracket for mounting of F90 sensors V1-G-2M-PVC Female cordset, M12, 4-pin, PVC cable V1-W-2M-PVC Female cordset, M12, 4-pin, PVC cable **Operating instructions** · Safety information This product may not be used in applications where personal safety depends on the function of the device. STOP This product is not a safety component as described in EU Machinery Direc-Warning tive. Sensor versions The F90 linear position measurement system is available in 2 versions. In the PMI...-F90-IU-V1 version, the position measuring system transmits current and voltage signals proportional to the position of the damping element at the outputs. The PMI...-F90-IE8-V15 version offers a current signal as well as the option of teaching in two switching points directly at the sensor independently of one another at the press of a button, which is then indicated on two switching outputs. Two additional LEDs indicate the output states of the two switching outputs. Version PMI...-F90-IU-V1 Output signals: 4 mA \dots 20 mA and 0 V \dots 10 V Only the current output or the voltage output may be used. The unused output must remain \square load free. Note Version PMI...-F90-IE8-V15 Output signals: 4 mA ... 20 mA and 2 programmable switching amplifiers Programming the PMI...-F90-IE8-V15 The rear of the PMI...-F90-IE8-V15 sensor has two small, slightly recessed push buttons for programming the switching points. The buttons are marked "teach in" and S1 for switching point S1 and S2 for switching point S2. To teach in a switching point, proceed as follows: The position detection damping element must be placed at the relevant position, i.e. the switching point that you wish to teach in. - Press the corresponding push button for at least two seconds. The associated switching state LED starts flashing to indicate that the sensor is now in "teach mode".

PEPPERL+FUCHS

2

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com The switching state LED then lights up constantly as long as the damping element is not moved.

The switching point is now taught in and the associated switching point changes to an active state within an actuator adjustment range of ± 1 mm around the taught switching point.

- If the switching point is not confirmed within 80 seconds, the sensor exits "teach mode" and
- continues operation with the previous values.
- Note

0 ∏

N

Damping element

The linear position measurement system is adapted perfectly to the geometry of the damping elements offered in our product range

- When using other damping elements, always make 0 ∏
 - sure that the active surface of the damping element
 - has a width of exactly 8 mm and covers the entire width of the sensor.
- · Installation and operation
 - Instructions on installation
 - Flush installation is possible
 - to extend the measuring range, units from the -F90 linear position measurement system can be connected in series (both behind and adjacent to one another) without a minimum distance.
 - The minimum distance between the measuring field (framed area on the sensor front) and mounting base or mounting elements on the damping element must be 3 mm.





Operating information

- The specified measurement accuracy is achieved with an actuator distance of 1 to 3 mm.
- If the damping element leaves the measuring area (illustration below):
- the last valid value is retained at the voltage output (PMI...-F90-IU-V1 only) until the damping element enters the valid area again.
- the last valid value is retained for 0.5 seconds at the current output (all types). The output then switches to a fault current of 3.6 mA until the damping element enters the valid area again.
- the switching amplifiers set to basic state after 0.5 seconds ("normally open")





· Defining the measuring range / measured position

The measured position of the damping element (actuator) is based on half of the width (center of the actuator). The measuring range starts and finishes when half the width of the actuator covers the measurement field marked on the sensor when the actuator makes a longitudinal movement (see left illustration above).



Accessories

Damping elements BT-F90-W



Straight cable:	
Angled cable:	

V15-G-2M-PVC (5-wire) V1-W-2M-PVC (4-wire) V15-W-2M-PVC (5-wire)

V1-G-2M-PVC (4-wire)

Mounting bracket MH-F90





PMI120-F90-IU-V1



www.pepperl-fuchs.com

fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com

