

# **Model Number**

# OQT120-R103-2EP-IO-0,3M-V1-L

Triangulation sensor (SbR) with fixed cable and M12 connector, 4-pin

## **Features**

- Miniature design with versatile • mounting options
- Multi Pixel Technology (MPT) -٠ flexibility and adaptability
- Reduction of device variety several • switch points within one sensor
- DuraBeam Laser Sensors durable and employable like an LED
- Reliable detection of all surfaces, independent of color and structure
- IO-link interface for service and process data

## **Product information**

The R103 series miniature optical sensors are the first devices of their kind to offer an end-to-end solution in a small single standard design - from thru-beam sensor through to a distance measurement device. As a result of this design, the sensors are able to perform practically all standard automation tasks.

The entire series enables sensors to communicate via IO-Link.

The DuraBeam laser sensors are durable and can be used in the same way as a standard sensor.

The use of Multi Pixel Technology gives the standard sensors a high level of flexibility and enables them to adapt more effectively to their operating environment.



# **Electrical connection**



**Pinout** 



# Indicators/operating means





1	Teach-in button	
2	Mode rotary switch	
3	Switch output indicator Q2	
4	Switch output indicator Q1	
5	Operating indicator	

Ι	Switch output 1 / switch point B
Ш	Switch output 1 / switch point A
III	Switch output 2 / switch point A
IV	Switch output 2 / switch point B
V	Keylock

Pepperl+Fuchs Group www.pepperl-fuchs.com

Refer to "General Notes Relating to Pepperl+Fuchs Product Information" USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com



1

Laserlabel

#### **Technical data**

General specifications Detection range Detection range min. Detection range max Adjustment range Reference target Light source Light type Laser nominal ratings Note Laser class Wave length Beam divergence Pulse length Repetition rate max. pulse energy Black/White difference (6 %/90 %) Diameter of the light spot Angle of divergence Ambient light limit Functional safety related parameters MTTF<sub>d</sub> Mission Time (T<sub>M</sub>)

Diagnostic Coverage (DC) Indicators/operating means Operation indicator

Function indicator

Control elements Control elements **Electrical specifications** Operating voltage Ripple No-load supply current Protection class Interface Interface type

Device profile Transfer rate **IO-Link Revision** Min. cycle time Process data witdh

SIO mode support Device ID Compatible master port type Output

Switching type

Signal output

Switching voltage Switching current Usage category Voltage drop Switching frequency

Response time Conformity Communication interface Product standard Laser safety Ambient conditions

Ambient temperature

Storage temperature **Mechanical specifications** Housing width Housing height Housing depth

8 ... 120 mm 8 ... 20 mm 8 ... 120 mm 20 ... 120 mm standard white, 100 mm x 100 mm laser diode modulated visible red light

LASER LIGHT, DO NOT STARE INTO BEAM

680 nm >5 mrad ; d63 < 1 mm in the range of 50 mm ... 250 mm 3μs approx. 3 kHz 15.2 nJ < 3 % at 120 mm approx. 2 mm at a distance of 120 mm approx. 1 EN 60947-5-2 : 30000 Lux

560 a

 $U_B$ 

 $I_0$ 

Ud

EN 60947-5-2 EN 60825-1:2014

15 mm

36.5 mm

26.7 mm

20 a

0%

LED green: constantly on - power on flashing (4Hz) - short circuit flashing with short break (1 Hz) - IO-Link mode LED vellow: constantly on - switch output active constantly off - switch output inactive Teach-In key 5-step rotary switch for operating modes selection

10 ... 30 V DC max. 10 % < 20 mA at 24 V supply voltage Ш

IO-Link (via C/Q = pin 4) Smart Sensor COM 2 (38.4 kBaud) 1.1 2.3 ms Process data input 2 Bit Process data output 2 Bit yes 0x110804 (1116164) A

The default setting is: C/Q - Pin4: NPN normally open, PNP normally closed, IO-Link Q2 - Pin2: NPN normally open, PNP normally closed 2 push-pull (4 in 1)outputs, short-circuit protected, reverse polarity protected, overvoltage protected max. 30 V DC max. 100 mA , resistive load DC-12 and DC-13 < 15 V DC217 Hz 2.3 ms IEC 61131-9

-40 ... 60 °C (-40 ... 140 °F) , fixed cable -25 ... 60 °C (-13 ... 140 °F) , movable cable not appropriate for conveyor chains -40 ... 70 °C (-40 ... 158 °F)



IEC 60825-1: 2007 certified. Complies with 21 CFR 1040.10 and 1040.11 except for deviations pursuant to Laser Notice No. 50, dated June 24, 2007

## Accessories

IO-Link-Master02-USB IO-Link master, supply via USB port or separate power supply, LED indicators, M12 plug for sensor connection

V1-G-2M-PUR Female cordset, M12, 4-pin, PUR cable

V1-W-2M-PUR Female cordset, M12, 4-pin, PUR cable

OMH-R103-01 Mounting bracket

V31-GM-2M-PUR Female cordset, M8, 4-pin, PUR cable

V31-WM-2M-PUR Female cordset, M8, 4-pin, PUR cable

OMH-R101-Front Mounting Clamp

**OMH-R101** Mounting Clamp

**OMH-4.1** Mounting Clamp

OMH-ML6 Mounting bracket

OMH-ML6-U Mounting bracket

OMH-ML6-Z Mounting bracket

Viounting Dracket Other suitable accessories can be found at www.pepperl-fuchs.com

Refer to "General Notes Relating to Pepperl+Fuchs Product Information" Pepperl+Fuchs Group www.pepperl-fuchs.com

USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com



Degree of protection	IP67 / IP69 / IP69K
Connection	300 mm fixed cable with M12 x 1, 4-pin connector
Material	
Housing	PC (Polycarbonate)
Optical face	PMMA
Mass	approx. 23 g
Cable length	0.3 m
Approvals and certificates	
UL approval	E87056 , cULus Listed , class 2 power supply , type rating 1
FDA approval	IEC 60825-1:2007 Complies with 21 CFR 1040.10 and 1040.11 except for deviations pursuant to Laser Notice No.

50, dated June 24, 2007

# **Curves/Diagrams**





# Preferences

#### Teach-In:

You can use the rotary switch to select the relevant switching threshold A and/or B for teaching in for switch signal Q1 or Q2.

The yellow LEDs indicate the current state of the selected output.

To store a threshold value, press and hold the "TI" button until the yellow and green LEDs flash in phase (approx. 1 s). Teach-In starts when the "TI" button is released.

- Successful Teach-In is indicated by alternating flashing (2.5 Hz) of the yellow and green LEDs.
- An unsuccessful Teach-In is indicated by rapidly alternating flashing (8 Hz) of the yellow and green LEDs.

After an unsuccessful Teach-In, the sensor continues to operate with the previous valid setting after the relevant visual fault signal is issued.

Different switching modes can be defined by teaching in the relevant distance measured values

for the switching thresholds A and B:

Single point mode:

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com





Window mode:



Every taught-in switching threshold can be retaught (overwritten) by pressing the "TI" button again.

Pressing and holding the "TI" button for > 4 s completely deletes the taught-in value. The yellow and green LEDs go out simultaneously to indicate that this procedure has been completed. Successful resetting is indicated by alternating flashing (2.5 Hz) of the yellow and green LEDs.

## **Resetting to Factory Default Settings**

Press the "TI" button for > 10 s in rotary switch position ,O' to reset to factory default settings. The yellow and green LEDs go out simultaneously to indicate the resetting.

Resetting process starts when the "TI" button is released and is indicated by the yellow LED. After the process the sensor works with factory default settings, immediately.

OMT:

- Factory default settings switch signal Q1: Switch signal active, window mode
- · Factory default settings switch signal Q2: Switch signal active, window mode

OQT:

- Factory default settings switch signal Q1:
- Switch signal active, BGS mode (background suppression)
- · Factory default settings switch signal Q2: Switch signal active, BGS mode (background suppression)

# **Configuration via IO-Link interface**

## Configuring different operating modes via the IO-Link interface

The devices are equipped with an IO-Link interface as standard for diagnostics and parameterization tasks to ensure optimum adjustment of the sensors to the relevant application. Four different operating modes can be set, among other features: Background suppression operating mode (one switch point):

• Detection of objects irrespective of type and color in a defined detection range. Objects in the background are suppressed.

active detection range	
	Background suppression

## Background evaluation operating mode (one switch point):

• Detection of objects irrespective of type and color against a defined background. Reliable detection of objects at close range (detection range >= 0 mm). The background serves as reference.

**Background evaluation** 

active detection range

# Single point mode operating mode (one switch point):

- Detection of objects irrespective of type and color in a defined detection range. Objects in the background are suppressed.
- The switch point corresponds exactly to the set point.



## Window mode operating mode (two switch points):

Detection of objects irrespective of type and color in a defined detection range. Reliable detection when object leaves the detection range.

· Window mode with two switch points.

active detection range

Foreground suppression

**Background suppression** 

### Center window mode operating mode (one switch point):

· Detection of objects irrespective of type and color in a defined detection range. Sets a defined window around a given object. Objects outside

	Refer to "General Notes Relating to Pepperl+Fuchs Product Information".				
4	Pepperl+Fuchs Group www.pepperl-fuchs.com	USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com	Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com	Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com	PEI



this window are not detected.

Window mode with one switch point. ٠

active detection range			
Foreground suppression	Background suppression		

# Two point mode operating mode (hysteresis operating mode):

• Detection of objects irrespective of type and color between a defined switch-on and switch-off point.

	active detection range	1
		Output
Output	 Hysteresis	Culput
Output		•

Inactive operating mode:

• Evaluation of switching signals is deactivated.

The associated IODD device description file can be found in the download area at www.pepperl-fuchs.com.

