

CE 

#### **Model Number**

#### RL61-8-H-2000-IR-Z/92/136

Background suppression sensor with 4-pin, M12 x 1 connector

#### **Features**

- Cost-optimized series for standard • tasks in a special design
- Compact design
- Wide range of mounting options • thanks to cubic housing design with M30 thread
- 360° high visibility LEDs ٠
- Programmable ON-delay, OFF-delay, and One-shot timers
- 4-in-1 output (push-pull)
- Version with infrared light

#### **Product information**

The Series 61 sensor family is a comprehensive product line, offering five sensing modes. Each sensor is equipped with four LEDs that are highly visible from all directions, indicating Power-On, target presence and marginal excess gain. The widely recognized, polycarbonate housing provides a IP67 protection degree rating. Color-coded labels are clearly printed on the housing to easily identify the sensing mode. DC models offer a 4-in-1 output while AC/DC models have a SPDT relay output rated to 3 A. All versions come standard with an integral multifunction timer, sensitivity adjustment and Light-ON/Dark-ON switch. Series 61 sensors are cross-talk protected and have a high degree of resistance to ambient lighting. Each sensor can be mounted via front and rear slots, rear dovetail guide or M30 x 1.5 mounting base. Additionally, cabled sensor models provide 1/2" - 14 NPT internal threads for use with flexible conduit.





#### **Electrical connection**



Indicators/operating means







5

# Operating display 1 2 Signal display

yellow 3 Sensing range adjuster 4 Time adjuster 5 **DIP-switches** 

green

# **Dimensions**

Pepperl+Fuchs Group www.pepperl-fuchs.com

Refer to "General Notes Relating to Pepperl+Fuchs Product Information" USA: +1 330 486 0001 fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 4411 fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091 fa-info@sg.pepperl-fuchs.com

ÐÐ



**Technical data** 

Detection range

General specifications

# RL61-8-H-2000-IR-Z/92/136

# 20 ... 2000 mm 20 ... 500 mm 20 ... 2000 mm

MPZB02 Mounting bracket with circular slots

Mounting bracket with vertical slots

Accessories

MPZB01

MPZB06 Ball and Swivel Mounting Bracket

MPZB07 Ball and Swivel Vertical Mounting Plate

# V1-G-BK2M-PUR-U Female cordset, M12, 4-pin, PUR cable

V1-W-BK2M-PUR-U Female cordset, M12, 4-pin, PUR cable

Other suitable accessories can be found at www.pepperl-fuchs.com

Detection range		20 2000 mm
Detection range min.		20 500 mm
Detection range max.		20 2000 mm
Adjustment range		500 2000 mm
Background suppression		max. + 10 % of the upper limit of the detection range
Light source		IRED
Light type		modulated infrared light , 850 nm
Black/White difference (6 %/90 %)		< 40 %
Diameter of the light spot		approx. 24 mm at a distance of 2000 mm
Angle of divergence		0.7 °
Ambient light limit		30000 Lux
Indicators/operating means		
Operation indicator		2 LEDs green
Function indicator		2 LEDs yellow ON: object inside the sensing range OFF: object outside the sensing range
Control elements		Light/Dark switch
Control elements		Detection range adjuster
Control elements		Time adjuster ( 0 50 ms )
Electrical specifications		
Operating voltage	UB	10 30 V DC
Ripple		10 %
No-load supply current	I <sub>0</sub>	≤ 35 mA
Protection class	Ū	II , rated voltage $\leq$ 250 V AC with pollution degree 1-2 according to IEC 60664-1 Output circuit basis insulation of input circuit according to EN 50178, rated insulation voltage 240 V AC
Output		
Switching type		light/dark on, switchable
Signal output		2 push-pull (4 in 1) outputs, short-circuit protected, reverse polarity protected
Switching voltage		max. 30 V DC
Switching current		max. 100 mA
Voltage drop	Ud	$\leq$ 2.5 V
Switching frequency	f	500 Hz
Response time		≤ 1 ms
Timer function		DIP-switch for selection of operating modes
Ambient conditions		
Ambient temperature		-40 55 °C (-40 131 °F)
Storage temperature		-40 70 °C (-40 158 °F)
Mechanical specifications		
Degree of protection		IP67
Connection		4-pin, M12 x 1 connector
Material		
Housing		PC (Polycarbonate)
Optical face		PMMA
Mass		approx. 120 g
Tightening torque, fastening screw	S	≤ 2 Nm
Compliance with standards and over	directi-	
Standard conformity		
Product standard		EN 60947-5-2:2007 IEC 60947-5-2:2007
Standards		EN 50178, UL 508
A		
Approvals and certificates		
UL approval		cULus
CCC approval		CCC approval / marking not required for products rated $\leq$ 36 V

Refer to "General Notes Relating to Pepperl+Fuchs Product Information"

Pepperl+Fuchs Group www.pepperl-fuchs.com

2



# **Curves/Diagrams**

# **Movement Characteristic**







# **Timer Functions**

Switching Type	Detection Status			Н			Light Received
L.ON	Operation Mode			┥┡	4		<ul> <li>No Light Received</li> </ul>
NO HEO Timer 9	No Delay (Timer OFF)						ON - OFF
NO LEG Timer 9	ON Delay	Ţ			-T		ON OFF
NO 440 Timer 9	OFF Delay		<b>→</b> T <b>→</b>			- T -	ON OFF
NO LLO Timer 9	One-Shot Delay	.T.			-		ON - OFF
OFF ON D OFF ON D OFF ON D D OFF ON D OFF ON D D OFF ON D D D OFF ON D D D OFF ON D D D D OFF ON D D D D D D D D D D D D D D D D D D D	ON Delay and OFF Delay	Ţ					ON - OFF
	N						
Switching Type	Detection Status Operation Mode						Light Received - No Light Received
							-
	Operation Mode					<u></u>	- No Light Received
D.ON Q LON Q LON O D.ON O D.ON O D.ON O D.ON O D.ON O D.ON O D.ON O D.ON O D.ON O D.ON O D.US O O D.US O O D.US O O D.US O O D.US O O D.US O O D.US O O O D.US O O O D.US O O O D.US O O O D.US O O O O O D.US O O O O O O O O O O O O O	Operation Mode No Delay (Timer OFF)	T.					<ul> <li>No Light Received</li> <li>ON</li> <li>OFF</li> <li>ON</li> </ul>
D.ON Q.E.ON Q.E.ON Timer 0 Timer 0 O.E.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D.ON D	Operation Mode No Delay (Timer OFF) ON Delay	Ţ					<ul> <li>No Light Received</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> </ul>
D.ON Q 440 Timer 01 Timer 01 Q 440 Timer 01 Q 440 Q 40 Timer 01 Q 440 Q 40 Timer 01 Q 440 Q 40 Q 4	Operation Mode No Delay (Timer OFF) ON Delay OFF Delay				┝╾╼┖╴ ┝╴		<ul> <li>No Light Received</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> <li>ON</li> <li>OFF</li> <li>ON</li> </ul>

Time (T) is adjustable from 0 to 50 ms

**PEPPERL+FUCHS** 

# **Adjustment Instructions**

### Intended use:

The transmitter and receiver are located in the same housing of Diffuse Mode sensors with Background Suppression. The suppression of objects outside the sensing range is achieved by arranging the angle between the transmitter and receiver (2 receiver elements).

Objects are detected independently of their surface structures, brightness and color, as well as the brightness of the background.

# Mounting instructions:

The sensors can be fastened directly with fixing screws or with a mounting bracket (not included with delivery).

The surface underneath must be flat to prevent the housing from moving when the sensor is tightened into position. We recommend securing the nut and screw in place with lock washers to prevent the sensor from going out of adjustment.

#### Adjustment:

After the operating voltage is applied, the green LEDs light up.

Align the sensor to the background. If the yellow LEDs are lit, the sensing range should be reduced with the sensing range adjuster until the yellow LEDs turn off.

#### **Object detection:**

Place the object to be detected at the desired maximum sensing range and align the light spot to it. If the object is detected, the yellow LED lights up.

If they do not light up, the sensing range must be adjusted on the potentiometer until the yellow LEDs light up indicating that an object is detected.

#### Cleaning:

We recommend cleaning the optical surface and checking all of the connections at regular intervals.

